

US EPA ARCHIVE DOCUMENT

<b>1. Incident Name</b>	<b>2. Date Prepared</b>	<b>3. Time Prepared</b>	<b>UNIT LOG ICS 214</b>	
Kalamazoo River/Enbridge Spill	12/20/2012	1610		
<b>4. Unit Name/Designators</b>	<b>5. Unit Leader</b>		<b>6. Operational Period :</b>	
Containment Branch Recovery Team 3 (CBR-3)	<b>Name:</b>	Dan Capone START/US EPA	<b>From:</b>	12/19/2012 0700
	<b>Position:</b>	Operations Section Chief	<b>To:</b>	12/19/2012 1530
<b>7. Personnel Roster Assigned</b>				
<b>Name</b>	<b>ICS Position</b>			
Dan Capone	Operations Section Chief			
Rex Johnson	Containment Branch Director			
Sean Kane	Field Team Lead/CBR-3			
<b>8. Activity Log</b>				
<b>Activity Area</b>	(MP 37.50 RDB Morrow Lake Delta, MP 26.00)	<b>LAT</b>	<b>LAT</b>	
		<b>Various</b>	<b>Various</b>	
		(DD.MMMM)	(DD.MMMM)	
<b><u>OIL OBSERVED</u></b>	<b>EXTENT OF OIL IMPACTED AREA</b>			
	<b>DENSITY OF OIL /SHEEN</b>			
<b>Total Collection Points</b>				
<b>Total Boom Deployed</b>				
<b>Activity</b>	<b><u>Weston/START CBR 3 Team Activity:</u></b>  General oversight documentation (photo and written) of Enbridge bathymetric survey team # 1 led by Luke Hodges (Stantec). Enbridge field team conducted transect measurements both upstream and downstream of the former E-1 boom location and collected a total of 25 survey points. Enbridge field team was relocated to operational area MP 26.00 RDB and conducted bathymetric survey measurements immediately downstream of sediment trap (pine tree line). A total of 10 survey points were collected in addition to one survey point collected within same operational area at MP26.00-D-19.			
<b>Health and Safety Issues</b>	Enbridge Field Team #1 ceased operations at 37.50 RDB due to inclement weather at approximately 1145 Hours			
<b>Comments</b>	Detailed field notes will be found in CBR-3 logbook.			

--	--